# Stamping Force Reduction with Inclined Punch

Rudi Kurniawan Arief

Departemen – eknik Mesin, Fakultas Teknik, Universitas Muhammadiyah - Sumatera Barat

Correspondence: rudikarief@umsb.ac.id

**Abstract.** Ideally processing of part using stamping machine using only 70-80 % of available force to keep machine in good shape for a long periods. But in some certain case the force may equal to or exceed the available maximum force so the company must sent the process to another outsource company. A case found in a metal stamping company where a final product consist of 3 parts to assembly with one part exceeded the force of available machine. This part can only process in a 1000 tons machine while this company only have 2 of this machine with full workload. Sending this parts outsource will induce delivery problems because other parts are processed, assembled and paint inhouse, this also need additional transportation cost and extra supervision to ensure the quality and delivery schedule. The only exit action of this problem is by reducing the force along the inclined surface that reduce stamping force as well. Inclined surface of punch also cause another major problems that the product becoming curved after process. This problems solved with additional flattening process that add more process cost but better than to outsource the process. Chisel type of inclining punch tip was choosen to avoid worst deformation of product. This paper will give the scientific recomendation to the company.

Keywords: metal stamping, force reduction, inclining punch, shearing process, cutting force

© 2017. BKSTM-Indonesia. All rights reserved

#### Preface

Ideally processing of part using stamping machine using only 70-80 % of available force to keep machine in good shape for a long periods. However, in some certain case the force may equal to or exceed the available maximum force so the company must sent the process to another outsource company. A case found in a metal stamping company where a final product consist of 3 parts to assembly with one part exceeded the force of available machine. This part can only process in a 1000 tons machine while this company only have 2 units of this machine with full workload. Other machine with 500 tons force available 4 units with medium load. To process this parts in 500 Tons machine will gain effeciencies in time production cost. Sending these parts outsource will induce delivery problems because other parts are processed, assembled and paint inhouse, this also need additional transportation cost and extra supervision to ensure the quality and delivery schedule.

The only exit action of this problem is by reducing the force tonnage. Punch or die inclining method is used to reduce the force. The incline punch will distributed the force along the inclined surface that reduce stamping force as well. The company already incline the punch slightly but not reducing a lot of force. View years ago, in the late 2005, Mr. Konishi, a senior engineer from head office Japan, give his advice to use the combination of flat and double shear type, but this advice never be applied until today. This paper will calculate theoritically the design that advised by the advisor to give the scientific recomendation to the company.

#### **Literature Review**



Figure 1. Force reduction with different punch geometries [3]

Force Reduction Methods. Sometime we face the problem of excessive stamping force that unaffordable by available press machine. Several methods can be used to reduce the stamping force such as inclined punch and staggered punch. Staggered punch usually applied for piercing process with multi punch, the punches then staggered or set in several different height to be able to cut simultaneously one after another. For blanking process with bigger size, usually inclined punch is used. This inclined punch surface also known as shear, because it works as the shearing process like a scissor. Inclined surface may reduce cutting force up to 25% [3].

Maximum stamping force can be reduced because punch pushing small amount of materials (b) step by step instead of pushing all materials together (a) as shown in figure 1 below.



Figure 2. Material pushing in stamping process [2]

Many type of inclined surface also applicable for punch surface with some advantages and disadvantages, the slug or blanking part might be deformed into the shapes of punch.



Figure 3. Punch inclined shape [3]

As the punch shape inclined, slug surface might be deformed according to inclined types. Figures below shown the slugs appearance after processed.



Figure 4. Slug deformation apearance [1]

As the cut-out part will be resemble the shape of it's punch, so it is advisable to use inclined punch for piercing process and inclined dies for blanking process. Figure 4 above explained that inclined dies surface will produced flat and better slug that suitable for blanking process to avoid deformation. But machinery and maintenance difficulties will be issues to be considered. The angle of inclined punch depend on material thickness [4]:

- 1. For  $t \le 3 \text{ mm} = h \le 2t$  and  $\alpha \le 5^0$
- 2. For t > 3 mm = h = t and  $\alpha \le 8^{0}$

Where H is height of inclined surface, t is material thickness.



Figure 5. Inclined punch

The higher shear angle applied on the punch, bigger possibility for workpiece to be deformed. Depend on tolerances and process planning, the deformation may acceptable if under tolerance specification, otherwise additional process will be required or deformation can be fixed in next step of the process.

**Stamping force formula.** Stamping force must be determined at the beginning to decide with press machine to use. This stamping force must be slightly lower than maximum press machine capacity for maintenance reason but somehow the stamping force were slightly higher. Under this situation inclined surfaced is applied.

Stamping force calculated by considering the length of cutting edge, material thickness and shear strength of material as formulated below:

$$P = L \times t \times Sc \tag{1}$$

Where P is cutting force (kgf), t is material thickness, L is length of cut, Sc is maximum cutting strength (see Table 1) and Sy is yield strength.

Table 1. Material maximum cutting strength (Sc)

Material	Maximum cutting strength, $S_c$
Alumunum, soft	(.75–.90) S <sub>v</sub>
Aluminum, hard	(.60–.65) S
Steel	(.75–.90) S
Stainless steel	(.68–.72) S.
Titanium alloys	(.6570) S

Note: Where  $S_v$  is the yield strength of the material.

Stamping force for inclined punch or dies operation is estimated as below :

$$P = 0,7 \times k \times L \times t \times UTS$$
(2)

Where:

P = Cutting Force (kgf)  $k = Constant value : 0,4 \sim 0,6 \text{ for } h = t$   $: 0,2 \sim 0,4 \text{ for } h = 2t$  t = Material thicknessUTS = Ultimate Tensile Strength

SC = (0,75-0,9) . Sy(3) SC = 0,8 . Sy<math display="block">SC = 0,8 . 240 = 192

## **Design Implementation**

The Case. The case was taken from Japanese owned metal stamping company located in Bekasi area, Indonesia. The assembly part consist of 4 stamping parts with welded assembly. Biggest stamping part made of 6mm thickness SPCC material is planned to have 4 stamping process. The process are: Blanking, 1<sup>st</sup> piercing, U- bending and 2<sup>nd</sup> pierce.



Figure 6. Finished part

The blanking process required force as estimated below:

Where t	= 6  mm
L	= 703,4mm
Sy	= 240 (for SPCC)
Sc	$= 0.8 \times Sy$ $= 0.8 \times 240$
P = 703.4	$= 192$ $4 \times 6 \times 192$
= 810.	$320 \text{ kgf} \approx 811 \text{ tons}$

From equation above means that this workpiece should be process in 1000 Tons stamping machine. Due to high utilities of 1000 Tons machine, the company tries to reduce the force by inclining the punch surface method. To process in other company is not an option because will require higher cost for transportation and stamping fee. The target is to reduce the force to 450 tons so this can be process with 500 tons stamping machine.



Figure 7. Total perimeter length of blank

**Case Countermeasures.** Inclined surface is chosen as force reducing method because this method may reduce the cutting force up to 50% and shear process produce lower shock and sound. With 6mm of material thickness the maximum inclined height should be equal to material thickness with inclined degree less than  $8^0$ .

Inclined punch with double shear method was chosen rather than inclined dies, the product will be deformed and buckling but the manufacturing and maintenance cost were much lower. Since the cutout parts will deform to shape of punch double shear punch then will produce NG blank parts. In the late 2005, Mr. Konishi, a senior engineer from head office Japan, give his advice to use the combination of flat and double shear type (Figure 7). This advice considering how to gain high force reduction but still keeping the good surface of the middle surface.



Figure 8. Inclined shape of punch

With this type cutting force and deformation of material can be reduce. Flat surface will act as conventional stamping and then continue by shearing to the rest of it. Double shear punch is suitable for piercing process because the scraps will deform to "V" shape and disposable while for blanking it will deformed the workpiece.

**Stamping Force Calculation.** The punch is divided into 3 parts (Fig. 3). Flat surface punch taken along 140mm, this is the position of flat

surface of part after bending. With this type, blanking process is divided into two stages; first stage is the flat surface punching then follow with shear punching.



Figure 9. Design of punch shapes

Cutting force will be P1 and P2+P3. Cutting force at P1:

Where:	t	= 6 mm
	L1	$= 140 \times 2 = 280 \text{ mm}$
	Sy	= 240 (SPCC)
	Sc	$=0.8 \times Sy$
		$=0.8 \times 240$
		= 192
P1	= 280 ×	5 6 × 192
	= 322.5	$60 \text{ kgf} \approx 323 \text{ tons}$

Cutting force at inclined punch (P2 & P3) is estimated as below:

 $P2 = P3 \tag{4}$ 

Where: h = t = 6mm k = 0,5 t = 6 mm (SPCC) L2 = 213 UTS = 270 (JIS G3141) P2 = 0,7 . 0,5 . 106,6 . 6 . 270 P2 = 120.771 kgf  $\approx$  120,8 tons

P2 + P3 = 241,6 tons

First stage cutting will require 323 tons of force and second stage form inclined punch required 121 tons of force so still applicable to process in 500 tons stamping machine.

This combination type cutting process are divided into two stages, where first stage required 323 tons of force and then follow by second process with shear method required 121 tons of force. Therefore, this process will be able to work in 500 tons stamping machine.

## Conclusions

The design use combination type of flat and inclined cutting surface. The calculation shows that cutting force reduced significantly and this part can be process in 500 tons machine compare with 1000 tons before. This combination may reduce the deformation of blank part rather than double incline (V-shaped). Inclined punch is choose for it ease of maintenance and manufacture. This design is theoretically acceptable and recommended to be manufactured.

### References

- [1] Suchy, I., 2006. Handbook of Die Design, 2nd Ed., Mc Graw-Hill.
- [2] Ahan, M.I. and Haque, S., 2011. Manufacturing Science, PHI Learning Private Limited, New Delhi.
- [3] <sup>3</sup>Altan, T. and Tekkaya, A.E., 2012. Sheet Metal Forming: Processes and Applications, ASM International, Ohio.
- [4] Boljanovic, V., 2004. Sheet Metal Forming Processes and Die Design, Industrial Press, New York.
- [5] Information on http://www.unipunch.com (02-07-2017)
- [6] hoi, H.S., Kim, B.M., Ko, D.C., 2014. Effect of clearance and inclined angle on sheared edge and tool failure in trimming of DP980 sheet, Journal of Mechanical Science and Technology, Vol. 28, Issue 6, 2319-2328
- [7] Bratus, V., Kosel, F., Kovac, M., 2010. Determination of optimal cutting edge geometry on a stamped orthotropic circular electrical steel sheet, Journal of Materials Precessing Technology 210, 396-407
- [8] Kumagai, Y., 1985. Instruction Manual on Die Designing and Manufacturing Technology, Sokeizai Center, Tokyo.